

## 2025 Q3 DCS Changes List

Standard	Revision Description
<b>Section 03</b>	
03 00 01 01	Single Circuit vertical configuration drawing revised.
03 01 01**	Revised Design Notes 3+4 and added design note 5.
03 01 20 **	Added DA bolts to drawings for 03 01 20 05/06
	Fixed typo in description table for 03 01 20 03
	Revised construction note 1
	Revised Drawing for 03 01 20 09
	Removed Guy adder from BOM
03 12 06 **	Revised Sheet 1 Description table
	ALL: Changed note callouts in BOMS and on drawings for additional notes added.
	ALL: Removed right adder symbol on DCS 07 and 12 callouts in BOMS
	New Standards: Sheet 3, 03 12 06 34-37 for double circuit double pins standards
	New Standards: Sheet 6, 03 12 06 48, 49, 50, 51, 80, 81, 82, and 83 for underbuild double pins standards
	Revised Note 20
<b>Section 09</b>	
09 00 04 01	<b>Corrected</b> typo for stock #1805040 for #2 Triplex (w/ #2 AAC neutral)
09 01 10	<b>Modified:</b> Construction Note #1: #2 triplex of max service drop lengths to 140ft, and 1/0 triplex and quadplex of max service drop lengths to 75ft.
09 01 12 00	<b>Removed</b> the standards and use DCS 08 01 10 00 instead
09 01 60	<b>Added</b> more details of description for each sleeve listed in the BOM.
	<b>Replaced</b> the stock #25 53 003 with stock #25 53 077.
	<b>Added</b> Snap - on splice cover on #4 to #2.
<b>Section 16</b>	
16 00 26	<b>Added:</b> Construction Note #9.
16 15 03	<b>Corrected:</b> Dimension
	<b>Revised:</b> Construction Note #5.
16 34 02**	<b>Revised:</b> Construction Note #5.
<b>Section 42</b>	
42 34 61 **	<b>Revised:</b> Sheet 2 Step 8: Extend the underline as shown.
	<b>Revised:</b> Sheet 5 Step 6: Correct words with hyphens as shown.
	<b>Revised:</b> Sheet 6 Step 9: Correct word with hyphen as shown.
	<b>Revised:</b> Sheet 8 Material Table: Delete "1" on Item H Column 17.