

Michael C. Hirschi, PhD, PE, CPESC, D.WRE
e-mail: MHirschi_CPESC@yahoo.com

September 17, 2009

AmerenIP
1901 Chouteau Avenue; POBox 66149; MC 602
St. Louis, MO 63166

Attn: Brian Martin


Re: Inspection of area under ILR10L332

Dear Brian,

Thanks for working with me on scheduling and conducting the educational inspection of the AmerenIP Former MGP Site last Friday. I hope it was worthwhile. As I mentioned when I was on-site, I had no areas of great concern, given the controls in place and the nature of the topography around the site. As I mentioned, there are products that you will find more satisfactory for the storm inlets. I'll send a link to those soon. The site meets the requirements of your permit and I consider it in compliance.

If anything comes up that you are concerned about or if I can be of assistance as work continues, please don't hesitate to contact me.

Sincerely,



Michael C. Hirschi

cc: Holly Hirschert
Bruce Stickers
Jacob Blanton